Choses

Miller MA Aviation



Propeller Log Book

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
10-18-91	O SMOH	Compliance With Overhaul SB 119	Through 177A
76 76	-14 The	ough 71-2 Replaced Blad	FACOR
2313	FRAME STATE		
- Line	10 A 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3		

Date: 10-18-91

13790-9724

	Major overhaul. All parts instpected and replaced as required. Work accomplished in accordance with manufacturer's instructions Model B2D34C207	This aircraft, airframe, aircraft engine, propeller or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair are on file at this repair station under:
ı	Hub S/N 742813	Work Order # 667 Date: 10-18-0
ı	Blade SN 1 B 34897 634905	Signed _ Mknekel to
	2 F 4002 Replant By	Miller Aviation, Inc. Repair Station No. DJER206D

		S. IIII S. III S	\$ 3 27 27 07 00
DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
5-18-93	28.6	disassembled prop. Bepoir	A A VOIS A
	SMOH	myordamore # 2 blade	ON SERVICE SER
		clean and Lub bearings	South Sturm or Avi
		reassembled using all new	a Relation with the set of the se
		gaskets and seals der 5.B	Held line
		192 retaining ring In spection	2 8 Porto
		check static balonce	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
		all work done I/Ak Service	I C STATE
		manual # 780630	San
			1 2 2 3
			11 438

		WINDLIAND OUT MENTS	
DATE	TACH	DESCRIPTION OF WORK	SIGNATURE
12/1/09	179.3	I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE W/ AN ANNUAL INSPECTION & HAS BEEN FOUND TO BE IN AIRWORTHY CONDITION Walter T Wiemer A&P97485383IA	
1-20-12	230.7	REMOVES From C- 1779 N 2193Q For O/4	AA 22359-17

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		The second secon	>
		20	
		BILLIAN STATE PROPERTY	THE STATE OF THE
811	to de la constitution de la cons		