



N 30639

Left ☐ Right ☐

AMERICAN PROPELLER SERVICE

 AMERITECH INDUSTRIES, INC.

Redding Municipal Airport

Redding, California 96002, U.S.A.

PHONE NUMBER (916) 221-4470 / (800) 292-PROP (7767)

FAA REPAIR STATION #NO3R717L / #NO3D717L

PROPELLER LOGBOOK

25, 1997.

Limitations and Conditions:

1. This approval should not be extended to other specific metal propellers of these models on which previously approved modifications are incorporated, unless it is determined that the interrelationship between this change and any other previously incorporated approved modifications will introduce no adverse effect upon the airworthiness of that propeller.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: April 05, 1996

Date reissued:

Date of issuance: March 10, 1997

Date amended: January 21, 1998



By direction of the Administrator


(Signature)

Anthony Socias
Manager, Airframe and Propulsion Branch
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

FAA Form 8110-2(10-88)

Page 1 of 10 Pages

This certificate may be transferred in accordance with FAR 21.47.

SERVICEABLE

GOVERNOR
UNIT

MCCAULEY
MAKE

C290D3K/T11
MODEL

840098
SERIAL NO.

The component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service.

Pertinent details of the repair are on file at this repair station under:

OWNER DAVE MOON

WORK ORDER NO. 4768

DATE 07/27/2001


SIGNED FOR

Tiffin Aire, Inc.
1778 West State Route 224
Tiffin, Ohio 44883
419-447-4263
800-553-7767 or 800-458-2487
FAX 419-447-4042
F.A.A. Certified Repair Station
Number DTXR341D

Called Mike
Tiffin Air
800-553-7767
overhaul \$2000
includes labor if fly out
8 days service
Labor install & balance
3 blade props 8600
new two blade is ~\$6100

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
4-12-96		AMERICAN PROPELLER SERVICE REPAIR STATION No. NO3R717L REDDING MUNICIPAL AIRPORT	

AMERICAN PROPELLER SERVICE

F.A.A. Repair Station No. NO3R717L ☒ / NO3D717L ☐
20208 Charlanne Dr., Redding, California 96002, U.S.A.

Work accomplished

COMPLETE OVERHAUL: Propeller disassembled,
cleaned, metric and dye penetrant inspected all parts
and blades. Blades ground, balanced, alodined,
painted and detailed. Propeller assembled, balanced
and functionally tested.
Complied with S.B. 106, 119, 137F, 140, 140-1, 154C and 192A.

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation regulations and is approved for return to service.

Pertinent details are on file at this agency under Work Order No. 24770

Invoice No. 40191

Dated April 12, 1996

Signed

[Signature]

Authorized Individual

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
January 7, '00	415.9	503.0 350. Inspection prop for	
	4194.4 T.T.	FAR 43 App B, para 100 hour inspection	
		and was approved for return to service	
		Rich E. Gaffney A/S 110387740	
Feb 11, 2001	559.2	PR 52-11-01 559.2 T.T. 4308.6	
		INSPECTION DONE I.A.W. PROCEDURES	
		OUTLINED IN FAR 43 APP. D. I CERTIFY	
		THAT THIS Propeller HAS BEEN	
		INSPECTED I.A.W. A 100 HOUR	
		INSPECTION AND WAS APPROVED FOR	
		RETURN TO SERVICE. 607.2 SMITH	
		Rich E. Gaffney A/S 112487740	

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
4-12-96		AMERICAN PROPELLER SERVICE REPAIR STATION No. NO3R717L REDDING MUNICIPAL AIRPORT	

AMERICAN PROPELLER SERVICE

F.A.A. Repair Station No. NO3R717L ☒ / NO3D717L ☐
20208 Charlanne Dr., Redding, California 96002, U.S.A.

Work accomplished

COMPLETE OVERHAUL: Propeller disassembled,
cleaned, metric and dye penetrant inspected all parts
and blades. Blades ground, balanced, alodined,
painted and detailed. Propeller assembled, balanced
and functionally tested.

Complied with S.B. 106, 119, 137F, 140, 140-1, 154C and 192A.

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation regulations and is approved for return to service.

Pertinent details are on file at this agency under Work Order No. 24770

Invoice No. 40191

Dated April 12, 1996

Signed

[Signature]

Authorized Individual

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		11/14/98 254.1 403209 INSPECTION DONE L.A.W. PROCEEDURE AND IN FAR 43 APP D. I CERTIFY THAT THE Propeller HAS BEEN INSPECTED L.A.W. 100 Hours INSPECTION AND WAS APPROVED FOR RETURN TO SERVICE 3362 5/10/98	
		RICHARD J. GAFFNEY 3362 5/10/98	
11-15-98	254.7	Prop Guard protective tape installed on leading edge according to Supplemental type Cert SR0052 NY	Raul M...

25, 1997.

Limitations and Conditions:

1. This approval should not be extended to other specific metal propellers of these models on which previously approved modifications are incorporated, unless it is determined that the interrelationship between this change and any other previously incorporated approved modifications will introduce no adverse effect upon the airworthiness of that propeller.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: April 05, 1996

Date reissued:

Date of issuance: March 10, 1997

Date amended: January 21, 1998



By direction of the Administrator

Anthony Socias
(Signature)

Anthony Socias
Manager, Airframe and Propulsion Branch
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

2
2
2
11
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES.

SERVICEABLE

PROPELLER UNIT MAKE

B2D34C211 779915
MODEL SERIAL NO.

The component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service.

Pertinent details of the repair are on file at this repair station under:

OWNER DAVID MOON

WORK ORDER NO. 15559

DATE 07/27/2001

SIGNED FOR

Tiffin Aire, Inc.
1778 West State Route 224
Tiffin, Ohio 44883
419-447-4263
800-553-7767 or 800-458-2487
FAX 419-447-4042
F.A.A. Certified Repair Station
Number DTXR341D

DATE

Date

Tach/Hobbs

REMOVED

SERVICES

COMPLETED

COMPLETED

COMPLETED

END

Work Performed By Tiffin Aire Inc.

Repair Station #DTXR341D. Work Order/Invoice # 15559

Signature

25, 1997.

Limitations and Conditions:

1. This approval should not be extended to other specific metal propellers of these models on which previously approved modifications are incorporated, unless it is determined that the interrelationship between this change and any other previously incorporated approved modifications will introduce no adverse effect upon the airworthiness of that propeller.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: April 05, 1996

Date of issuance: March 10, 1997

Date revised:

Date amended: January 21, 1998



By direction of the Administrator

Anthony Socias
(Signature)

Anthony Socias
Manager, Airframe and Propulsion Branch
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

FAA Form 8110-2(10-66) Page 1 of 10 Pages

This certificate may be transferred in accordance with FAR 21.47.

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
Jan. 7 '00	415.9	SMolt	
5-14-2013	886.7	404.6 SMolt TT UNK. Inspected propeller IAW the scope and detail of FAR 43 App D. I certify that this propeller has been inspected IAW a 100hr inspection and found to be in airworthy condition. <i>Reid J. Buffney</i> AIP 3345444	
5-11-2015	903.4	^{RE} 951.7 / certify that this propeller has been inspected IAW a 100 hour inspection and found to be in airworthy conditions	<i>Reid J. Buffney</i> AIP 3345444
951.7 SMolt RB			

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
June 7, 2017	903.6	Inspected propeller IAW a 100 hr inspection and found to be in airworthy condition.	Richard B. Brey A+P 3345444
951.95 PMH			
See airplane log for 2018 propeller entry.			
12-20-2019	915.7	965.25 PMH Propeller inspected IAW a 100 hour inspection and found to be in airworthy condition.	R. Brey A+P 3345444
		N30639 March 11, 2021 Tach 919.9 TSMOH 969.4	
		Dressed Prop. Inspected Spinner and backing plate.	
		I certify that this prop has been inspected IAW a 100 Hr. inspection and was determined to be in an airworthy condition.	
		David Bright A&P 2815502IA	David P. Bright

23, 1997.

Limitations and Conditions:

1. This approval should not be extended to other specific metal propellers of these models on which previously approved modifications are incorporated, unless it is determined that the interrelationship between this change and any other previously incorporated approved modifications will introduce no adverse effect upon the airworthiness of that propeller.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: April 05, 1996

Date received:

Date of issuance: March 10, 1997

Date amended: January 21, 1998



By direction of the Administration

Anthony Socias
(Signature)

Anthony Socias
Manager, Airframe and Propulsion Branch
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

FAA Form #110-2(10-68)

Page 1 of 10 Pages

This certificate may be transferred in accordance with FAR 21.47.

[illegible]

David Bright A&P 2815502IA

David P. Buehl

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
	N30639 Nov 17, 2023 Tach 924.4	TSMOH 973.7 Dressed Prop. Inspected Spinner and backing plate. All Ads checked up to date.	
	N30639 Nov 17, 2023 Tach 924.4	TSMOH 973.7 I certify that this prop has been inspected IAW a 100 Hr. inspection and was determined to be in an airworthy condition.	
		<i>David Bright</i> David Bright A&P 28155021A	

25, 1997.

Limitations and Conditions:

1. This approval should not be extended to other specific metal propellers of these models on which previously approved modifications are incorporated, unless it is determined that the interrelationship between this change and any other previously incorporated approved modifications will introduce no adverse effect upon the airworthiness of that propeller.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: April 05, 1996

Date of issuance: March 10, 1997

Date reissued:

Date amended: January 21, 1998



By direction of the Administrator

Anthony Socias
(Signature)

Anthony Socias
Manager, Airframe and Propulsion Branch
New York Aircraft Certification Office

(Title)

2

11

11

11

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number SP00582NY

This certificate issued to

Prop-Guard Aerospace, Inc.
922 Groton Avenue
Cortland, NY 13045

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 119 of the Civil Air/Federal Aviation Regulations.

Original Product -- Type Certificate Number:

See Attached Approved

Make:

Model List (AML)

Model:

Model List (AML)

Description of Type Design Change:

Installation of Prop-Guard Polyurethane Protective Tape on the leading edge of metal propellers in accordance with the instructions contained in Prop-Guard Installation Instructions, Document No. FP1001, dated February 25, 1997.

Limitations and Conditions:

1. This approval should not be extended to other specific metal propellers of these models on which previously approved modifications are incorporated, unless it is determined that the interrelationship between this change and any other previously incorporated approved modifications will introduce no adverse effect upon the airworthiness of that propeller.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: April 05, 1996

Date issued:

Date of issuance: March 10, 1997

Date amended: January 21, 1998



By direction of the Administrator

Anthony Socias
(Signature)
Anthony Socias
Manager, Airframe and Propulsion Branch
New York Aircraft Certification Office

(Title)

PROPELLER MAINTENANCE RECORDS

Log No. 2

Aircraft Registration No. N30639

Propeller Manufacturer McCaughey

Hub Model 2034C202

Blade Design No. 82 PA-1

Hub Serial No. 780109

Blade Serial No's.

1. _____
2. _____
3. _____
4. _____

Pitch Range:

High 26.0° Low 12.1°

Feather _____ Reverse _____

Governor Manufacturer McCaughey - CESSNA

Model No. C161031-0105

Serial No. _____

Date installed on aircraft _____

Time Between Overhauls (TBO) _____ Hours

If used on multi-engine aircraft:

- | | |
|--------------------------------|-------------------------------|
| <input type="checkbox"/> Right | <input type="checkbox"/> Left |
| <input type="checkbox"/> Front | <input type="checkbox"/> Rear |

(All applicable information must be filled in)

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
	3221.89	1367.89	0002.1	TOTALS brought forward from previous page
	New Propeller. installed By Aircraft			
	Tech. Svc. on. Nov. 8 1979 TT 3219.69			
	Ref. to old. Log Book. #2.			
				W. Kozany 73406265
7/15/82	152.11	Nov. 152.11		Cleaned. & Burnished prop
				B. Kozany 73406265

NEW ENGLAND PROPELLER SERVICE, INC.

LOT #6, EAST HADDAM INDUSTRIAL PARK
EAST HADDAM, CT 06423
F A A REPAIR STATION #3580

RATINGS
PROPELLER CLASS 1-2
LIMITED ACCESSORY

SERVICABLE

CUSTOMER Brookfield Aviation
MFG McCaughey COMPONENT Propeller
REMARKS Disassembled, cleaned and inspected. Repaired and matched blades and polish. Reassembled, greased, set angles track, balanced and painted.
ANGLES AT 30 STA. LO: 12.1 HI: 26.0 FEA:

S/N 78019
Re installed
5516
7/15/82
41490602552

SUB-TOTALS this page

TOTALS—Carry forward to next page

