

THE **adlog**<sup>TM</sup> AIRCRAFT  
MAINTENANCE  
RECORDKEEPING  
SYSTEM

**PROPELLER  
MAINTENANCE  
RECORDS**

DATE

TOTAL  
TIME  
IN  
SERVICETOTAL  
TIME  
SINCE  
OVERHAULTACH OR  
RECORDING  
METER  
TIMEDESCRIPTION OF WORK PERFORMED—  
SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORKAviation Plus LLC  
262-656-1260  
Aviationplusllc.com


06/30/15 N1548H Tach 5813

Reinstalled propeller after reseal by Aircraft Propeller Service, WO# 117505.

  
Robert Russell 3411885IA
Aviation Plus LLC  
262-656-1260  
Aviationplusllc.com

09/11/2015 N1548H Tach 5838 TTP 5838 SMOH 1040

All routine items checked per inspections sheets. I certify that this propeller has been inspected in accordance with annual inspection and was determined to be in an airworthy condition.

  
Robert Russell 3411885IA

8/4/16

58683

100HR INSPECTION COMPLETED

Graham L Goad A&amp;P 2801174

Aviation Plus LLC  
262-656-1260  
Aviationplusllc.com

07/18/2017 N1548H Tach 5900 TTP 5900 SPOH 1102

All routine items checked per inspection sheets. I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.


  
Robert Russell 3411885IA

Propeller McCauley B2D34C207 s/n 771062

7/26/2018 Tach Time 5929.0 N1548H

This propeller inspected per 100hr inspection in accordance FAR 43 Appendix D and found to be airworthy at this time.

Graham L Goad 2801174 A&amp;P


Aviation Plus LLC  
262-656-1260  
Aviationplusllc.com

08/01/2019 N1548H Tach 5981 TTP 5981 SMOH 1183

Dynamic balance done to .1 IPS. All routine items checked per inspection sheets. FAR43 App D. I certify that this propeller was inspected in accordance with an annual inspection and was determined to be in airworthy condition.

  
Robert Russell 3411885IA

... forward to next page

DATE

9-3-2020

McCauley B2D34C207

S/N: 771062

Work performed: Inspected propeller hub, blades, spinner, and bulkhead, no defects noted. This propeller has been inspected IAW an annual inspection As per McCauley maintenance manual and FAR43 Appendix D.

Justin Frunk AP3685162IA




**SUB-TOTALS** this page**TOTALS**-Carry forward to next page