


No. 2



FAA CRS# W59R659N

A/C N# 177LR
Prop M/N BZD34C207B
Prop S/N 861025

PROPELLER LOGBOOK

PROPELLER INFORMATION

Check applicable box

☐ Right Engine

☐ Left Engine

Hub Model BZD34207B

Hub Serial 861025

Blade Model G78TCA-0

Blade Serial #1 GF037

Blade Serial #2 GF040

Blade Serial #3 N/A

Blade Serial #4 A

Diameter 77.7"

Governor Model _____

[illegible][illegible]

3. Form Tracking Number: 28700	
5. Work Order/Contract/Invoice Number: 6390	
59N	12. Status/Work: Overhaul
1. Serial/Batch Number: 861025	
3, S/L 98-5, 05-08, 07-07, 08-01. Refer to work	
Service ☐ Other regulation specified in Block 13 Use specified in Block 13, the work identified in Block 13 was accomplished in accordance with Title 14, part 43 and in respect to that work, the items are in service.	
21. Approval/Certificate No.: W59R659N	23. Date (m/d/y): Oct 3, 2008
authority to install the part/component/assembly. Different than the airworthiness authority of the country of origin/assembly from the airworthiness authority of the country of origin/assembly. an installation certification issued in accordance with the	

NSN: 0052-00-012-9005

MAINTENANCE RECORD

Date	Time Run	T.T.S.O.	Description of all operations pertaining to A/Ds S/Bs, S/Ls, and minor adjustments	Signature
10/3/08		0.0	Major overhaul and static balance	this date.
			Refer to W/O # 5390 and 8130-3 # 28700 for details and approval for return to service.	
				<i>James W. Hall</i>
				FAA CTS# W59R659N
10-21-08		Tach 2377.	INSTALLED old propeller back on & started	
			RAN ENGINE NO OIL Leaks noted	James W. Hall 527944430 ACP.
11-2-09		Tach 2443.2	checked & leaks over propeller and RETURN TO service.	James W. Hall 527944430 ACP J.A.

Date	Time Run	T.T.S.O.	Description of all operations pertaining to A/Ds S/Bs, S/Ls, and minor adjustments	Signature
------	----------	----------	--	-----------

N177LR 12-15-2011 Tach:2511.49

- Resafteied prop bolts properly

- Dressed prop for nicks

-I certify that this propeller was inspected I/A/W an ANNUAL INSPECTION and found to be in an AIRWORTHY condition.

Rusty Gill  AP2770994IA

134.49 SP0H

1944.29 TT18

JUNE 26, 2012	17.51	152.0	1961.8 TTIS (LAST O/H OCT 3, 2008)
			US LOG CLOSED AND TTIS 1961.8 HRS
			AND 152.0 HRS TTSS TRANSCRIBED IN NEW
			CANADIAN LOG BOOK @-GTLR
			B. Boulet M 206135

Date	Time Run	T.T.S.O.	Description of all operations pertaining to A/Ds S/Ps, S/Ls, and minor adjustments	Signature
------	----------	----------	--	-----------

[illegible]

Date	Time Run	T.T.S.O.	Description of all operations pertaining to A/Ds S/Bs, S/Ls, and minor adjustments.	Signature

[illegible]

Date	Time Run	T.T.S.O.	Description of all operations pertaining to A/Ds S/Bs, S/Ls, and minor adjustments	Signature
------	----------	----------	--	-----------

[illegible]

Warner Propeller & Governor Co.

Mailing: P.O. Box 11278
Tucson, Az. 85734-1278

Shipping: 5102 S. Country Club Rd.
Tucson, Az. 85706

Telephone: (520) 294-5671 Fax (520) 294-1114

FAA CRS# W59R659N