

Company
Make/Model
Tail #
Serial #

WRIGHT AVIATION MAINTENANCE
Cessna - 177RG
N177RG

airframe

ENGINE LOG BOOK



Engine Log & Maintenance Record

LOG #: 1

RECORD OF Lycoming 10-390-A1A6
(MAKE) (MODEL) (SERIAL)

AIRCRAFT REGISTRATION NUMBER: N 177TG

FROM 4/21 2019 TO _____ 20____

DETAILING TIME FROM _____ TO _____
(HOURS) (HOURS)

If used on a multi-engine aircraft: _____ Right _____ Left _____ Front _____ Rear

Rebuilt Engine Certificate of Conformance

This is to certify that the engine as described hereinafter has been REBUILT in accordance with the applicable Lycoming specifications. It has been determined airworthy to return to service and is in a condition for safe operation. All applicable Federal Aviation Administration Airworthiness Directives and Lycoming Service Publications have been complied with. All accessories as part of the type certificate are new or newly rebuilt. Refer to enclosed Form ET001 for applicable accessory part numbers and serial numbers.

LYCOMING

Part Number RENPL-RT10592
Serial Number RL-833-80E
Engine Model IO-390-A1A6
Work Order KM726451
Total Time 0

Low R. Adams 3/7/19
Authorized Representative Date

Production Certificate #3

652 Oliver Street Williamsport, PA 17701 U.S.A.
Lycoming Engines is a division of Avco Corporation

Form 2481 Rev 05/13

Engine Log

Serial # _____

Date	Time Run (Hours)	Total Time Since Overhaul	Repairs, Adjustments, Service, Remarks	Signature	Licence #
------	------------------	---------------------------	--	-----------	-----------

BROUG

MAKE: Lycoming
MODEL: IO-390-A1A6
S/N: RL-833-80E
REG. NO.: 177TG
WORK ORDER: 0233

Wright Aviation Maintenance
47 Long Meadow Rd.
Oxford, CT 06478
Phone: 203-556-3860

DATE: 4/2/19
A/C HOBB: N/A
ENG TT: 0.0
TSMOH: 0.0

ANNUAL ENGINE LOGBOOK ENTRY

Annual Inspection performed IAW Part 43 Appendix D and manufacturers service manuals.
AD's searched and complied with, thru Tdata 2019-7

The following services were provided: Engine installed in N177TG, serial # 177RG0999 IAW Lycoming STC SA10944SC and Slick start STC SA593CH and Cessna service manuals. Inspected exhaust system and engine mount. Engine was run up. Operation and leak check OK.

The following new parts have been installed: (1) CH48108-1 Oil Filter, (8) qts. 20W-50 Phillips mineral oil.

I certify that this engine has been serviced IAW an Annual Inspection, and was determined to be airworthy condition on the date shown above.

Authorized Signature: _____

Devon Chapin

Devon Chapin A&P67484333IA

MAKE: Lycoming
MODEL: IO-390-A1A6
S/N: RL-833-80E
REG. NO.: 177TG
WORK ORDER: 1061

Wright Aviation Maintenance
47 Long Meadow Rd.
Oxford, CT 06478
Phone: 203-556-3860

DATE: 4/17/20
A/C HOBB: N/A
ENG TT: 28.6
TSMOH: 28.6

ANNUAL ENGINE LOGBOOK ENTRY

Annual Inspection performed IAW Part 43 Appendix D and manufacturers service manuals.
AD's searched and complied with, thru Tdata 2020-08

The following services were provided: Engine was run up. Oil drained. Sample taken. Oil and filter changed. Oil filter cut open, no debris noted. Check magneto timing. Inspected exhaust system and engine mount. Engine was run up. Operation and leak check OK.

The following new parts have been installed: (1) AACH48108-1 Oil Filter, (8) qts. 20W-50 Phillips mineral oil.

The following compression readings were taken: L/C 1)80 2)80 3)80 4)80

I certify that this engine has been serviced IAW an Annual Inspection, and was determined to be airworthy condition on the date shown above.

Authorized Signature: _____

Mark Lloret

Mark Lloret A&P3212662 IA

Page Total: _____

Brought Forward: _____

Total to Date: _____

All repair data must bear the endorsement of a certified mechanic, and his/her rating and certificate number MUST be shown.

Engine Log

Serial # _____

Date	Time Run (Hours)	Total Time Since Overhaul	Repairs, Adjustments, Service, Remarks	Signature	Licence #
------	------------------	---------------------------	--	-----------	-----------

MAKE: Lycoming
MODEL: IO-390-A1A6
S/N: RL-833-80E
REG. NO.: 177TG
WORK ORDER: 1455

Wright Aviation Maintenance
47 Long Meadow Rd.
Oxford, CT 06478
Phone: 203-556-3860

DATE: 6/21/21
A/C HOBB: N/A
ENG TT: 40.8
TSMOH: 40.8

ANNUAL ENGINE ENTRY

Annual Inspection performed IAW Part 43 Appendix D and manufacturers service manuals.
AD's searched and complied with, thru Tdata 2022-13


The following services were provided: Engine was run up. Oil drained. Sample taken. Oil and filter changed. Oil filter cut open, no debris noted. Inspected exhaust system and engine mount. Engine was run up. Operation and leak check OK.

The following new parts have been installed: (1) CH48110-1 Oil Filter, (8) qts. 20W50 Phillips Victory Oil

The following compression readings were taken: L/C: 1)70 2)75 3)75 4)74

I certify that this engine has been serviced IAW an Annual Inspection, and was determined to be airworthy condition on the date shown above.

Authorized Signature:



Mark Lloret A&P3212662 IA

MAKE: Lycoming
MODEL: IO-390-A1A6
S/N: RL-833-80E
REG. NO.: 177TG
WORK ORDER: 1681

Wright Aviation Maintenance
47 Long Meadow Rd.
Oxford, CT 06478
Phone: 203-556-3860

DATE: 7/6/22
A/C HOBB: N/A
ENG TT: 45.6
TSMOH: 45.6

Annual Inspection performed IAW Part 43 Appendix D and manufacturers service manuals.
AD's searched and complied with, thru Tdata 2022-14


The following services were provided: Engine was run up. Oil drained. Sample taken. Oil and filter changed. Oil filter cut open, no debris noted. Sonic clean injectors. Inspected exhaust system and engine mount. Adjust magneto timing. Engine was run up. Operation and leak check OK.

The following new parts have been installed: (1) CH48110-1 Oil Filter, (8) qts. 20W50 Phillips Victory Oil

The following compression readings were taken: L/C: 1)78 2)78 3)78 4)78

I certify that this engine has been serviced IAW an Annual Inspection, and was determined to be airworthy condition on the date shown above.

Authorized Signature:



Devon Chapin A&P67484333IA

Page _____

Brought Forward _____

Total to Date: _____

All repair data must bear the endorsement of a certified mechanic, and his/her rating and certificate number MUST be shown.