

***LYCOMING***

A Textron Company

# ENGINE LOG

**SSP-1872-1**

N52713 - #3



**LYCOMING**

A Textron Company

652 Oliver Street  
Williamsport, PA 17701 U.S.A.  
570/323-6181

# ENGINE LOG AND MAINTENANCE RECORD

RECORD OF LYCOMING 10-360-A1B6D L-27321-51A

MAKE

MODEL

SERIAL

FROM 12-23 20 03 TO \_\_\_\_\_ 20 \_\_\_\_\_

DETAILING TIME FROM \_\_\_\_\_ TO \_\_\_\_\_  
HOURS HOURS

SSP-1872-1

© 1994 by Textron Lycoming "All Rights Reserved"

October 1994

# **LYCOMING**

A Textron Company

652 Oliver Street  
Williamsport, PA. 17701 U.S.A.

TLRED-489

(Rev. 3-02)

This engine has been overhauled/~~rebuilt~~ in accordance with the applicable Lycoming manuals. All applicable Federal Aviation Administration Airworthiness Directives and Lycoming Service Bulletins have been complied with. All parts have been inspected and have been determined airworthy to return to service. All accessories as part of the type certificate are either new or newly overhauled. Refer to enclosed Form ET001 for applicable accessory part numbers and serial numbers.

Engine Model: IO-360-A1B6D  
Serial #: L-27321-51A  
Total Time: 1123.0  
Work Order #: GJ214685  
Date Completed: OCT 21 2003

Authorized Signature

**Lycoming Engines**

652 Oliver Street  
Williamsport, PA 17701  
Repair Station: EJ1R115K

# ENGINE DESCRIPTION

Mfgr.	LYCOMING	Place	Williamsport, PA 17701	Date	
Type		Model		Serial No.	
Rated H.P.		Max. H.P.		Weight (Dry)	
Rated R.P.M.		Max. R.P.M.		Oil Pressure	
Bore		Stroke		Displacement	Cu. In.
Compression Ratio		Supercharger Ratio			
Reduction Gear Ratio					
Propeller		Hub Design		Hub Serial No.	
Blade Design		Blade Serial No.		Blade Serial No.	
Max. Hub H.P.		Max. Blade H.P.			
Pitch		Diameter		Length	
Name					
Address					

## ENGINE LOG

Serial No. L-27331-51A

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
12/23/2003	TACH	1772.4	INSTALLED ENGINE IO-360-A1B6D ON AIRCRAFT N 52713, S/N 1255. NEW HOSE KIT AQ177-007, NEW MOUNTS T96513-19, REPLACED BAFFLE SEALS, SERVICED WITH 7 QUARTS 10.5 MINERAL OIL AEROSHELL GROUND RUN, NO LEAKS NOTED. REPLACED VACUUM PUMP <i>John Peters 22 10218 PA</i>		
Page Total			All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.		
Brought Forward					
Total to Date					

## ENGINE LOG

Serial No. \_\_\_\_\_

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
			Page Total	All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.	
			Brought Forward		
			Total to Date		







