

PROPELLER MAINTENANCE RECORD

LEFT ENGINE	RIGHT ENGINE
Hub Model <u>B2D34C207</u>	Hub Model
Blade Design 78TCA-0	Blade Design
Diameter	Diameter
Hub Ser. No. 774493	Hub Ser. No.
Blade Ser. Nos. 22 1204 14 1200 171 171 171 171 171 171 171 171 171 1	Blade Ser. Nos.
No. 1 B 7/862	No. 1
No. 2 B 7/869	No. 2
No. 3 YO GENERAL WAR WAR GENERAL WAR WAR GENERAL WAR WAR GENERAL WAR WAR WAR W	No. 3
No. 4	No. 4
No. 5 ON A SIVIES TELLESCOPE ON A SIVIES WE	No. 5
PITCH RANGE	PITCH RANGE
High 27.5 Low 12.9	High Low
Feather Reverse	Feather Reverse
Governor Model	Governor Model

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
5-24-10	750	B2D34C207/28TCA-0	5/2774493
		MAJOR OVERHAUL BLADES	REFINISHED, PARTS FLORESCENT
		PENETRANT INSPECTED, MA	GNAFLUXED, & REPLACED WHERE
		REQUIRED, PROPELLER TR. GREASED & PAINTED COMP	ALXED, BALANCED SET ANGLES
		8130-3 FORM.	
		AUTHORIZED BY	W/0#CR-36941
		fall	- president
		FOR NEW ENGLAND PROF	ELLER SERVICE INC
		EASTHAI	
			TON # RC2R130L
		1-800-8	78-6377
			

DATE	TACH	DESCRIPTION OF WORK	SIGNATURE
	Time		
	PROP MODEL: B2D34C207	North American Flight Services	DATE: 13 July, 2010 ACTSN
	PROF S/N: 774493 REG. NO: N52713 WORK ORDER: 2439-05-2010	Repair Station No. MOWR725J 405 Graceficial Avenue Ballston Spa, NY 12020 Phone: 518-885-5470	PROP TT. TACH: 2872.2
V3 .	Prop Entries INSTALLED OVE PROCEDURES, I	RHAULED PROPELLER I/A/W CESSNA RG177 MAINTENA P/N B2D34C207/78TCA-0, S/N 774493.	NCE MANUAL
	The aircraft, airframe current regulations of DATE: 13 July, 2010	e, aircraft engine, propeller, or appliance identified above was replied of the Federal Aviation Administration and approved for rehapito services and approved for rehapito services.	and inspected in accordance with oe Work Order: 2439-05-2010
		Januariidenbrandt Refulfied Repair Station No. NOMR725J	Printed by EBIs 3 (datcomed a com)

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
-	Luguo t	3 2010 TACH 2877.6	77 Prop 820,4 suy
	0	Expeller inspected for	condition - Blacker
	Examin	of for dominge - reales and	I found more
	Pun	eles determened to be	in anworthy condu
			60
		7	on Valent 934455441
-		7.06	
Tur	e 9, 2011	. 2985.0	
	Propelle	inspected for condition.	e leaks. cleand
	Blacked	Elected la nice Repullon	detumend to
	bein	genworthy condition.	
		Som fast	(1) 93445544 IA
		you vues	

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
Dec	11, 2011 7	ach 3061.6 Hobs 2130	D. 4 TTSPOH 9044
	People	Inspected for usual	andition - operation
	and from	of to be in airball	to condition
			Jon Toward 9345
Janu	usus 1, 2015	Tach 3148.3 TTS	POH- 991.1 HPS.
1	Spenner	Pack 3/48.3 TTS	vally eveneted by
	lease & condi	tion diesed blades of	NICES. PLOTO
	determented	to be in assorthy	ordition
		To	MARATA 934455441#

On-Site Aero Services, LLC Eagle's Nest Airport (31E)

McCauley B2D34C207 S/N 774493

May 1, 2016 Tach: 3484.4 SMOH:612.2

- Complied with 100 hour inspection & servicing IAW Cessna inspection checklist & requirements of 14CFR 43 Appendix D.
- AD Compliance checked thru FAA Bi-Weekly 2016-10
- Checked blade track, touched up paint as required

I certify that this Propeller has been inspected in accordance with a 100 Hour Inspection and was determined to be in alrworthy condition.

Thomas J. Gray 2777905 A&P &~

PERTAINING TO AIRWORTHINESS DIRECTIVES.

"WS, SERVICE LETTERS.

On-Site Aero Services, LLC Eagle's Nest Airport (31E)

McCauley B2D34C207 S/N 774493

May 12, 2017 Tach: 3484.4 Tach: 3566.9 SMOH: 694.7

- Compiled with 100 hour impection & servicing Ref. Cessna inspection checklist & requirements of 14CFR 43 Appendix D.
- AD Compliance checked thru FAA Bi-Weekly 2017-10
- · Checked blade track, touched up paint as required

I certify that this Propeller has been inspected in accordance with a 100 Hour Inspection and was determined to be in airworthy condition.

Thomas J. Gray 2777905 A&P

On-Site Aero Services, LLC Engle's Nest Airport (31E)

McCauley B2D34C207 S/N 774493

June 1, 2018 Tach: 3638.1 SMOH: 765,9

- Complied with 180 hour inspection & servicing Ref. Cessna inspection checklist & requirements of 14CFR 43 Appendix D.
- AD Compliance checked thru FAA Bi-Weekly 2018-12
- Checked blade track, touched up paint as required

I certify that this Propeller has been inspected in accordance with a 100 Hour Inspection and was determined to be in airworthy condition.

Thomas J. Gray 2777905 A&P

REPORTED INCOME. SIGNATURE OF THE PROPERTY OF

REGIONAL AIRPORT. MONTICELLO, IA FAA CERTIFIFO REPAR STATION #KIOR999K*	DATE 4-6-20 WO NO 13945	AIRWORTHY CONDITION	INSPECTION AND WAS DETERMINED TO BE IN ==	I CERTIFY THAT THIS AND SPANTHENOWE HAS BEEN	-00 co-	REGIONAL AIRPORT, MONTICELLO, IA FAA CERTIFIED REPAIR STATION #K02R959K	BY SOUTH TO WINDOW INC	TACH HOURS 3 (267) 5 13734	INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION	DESCRIPTIONED TWO BRATTHIS AINCHA THE WORLD HASISMATURE
---	-------------------------	---------------------	---	--	---------	---	------------------------	----------------------------	--	---

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		propoeler	
	I CERTIFY THAT THE	SAIRCRAFT/ENGINE HAS BEEN	
- IN	INSPECTED IN ACCOR	WAS DETERMINED TO BE IN	
	20	FIT-7	
	ACH HOURS	N.O. NO. 14/15	
B	MONTIC	ELLO AVIATION, INC.	
*	REGIONAL A	RPORT, MONTICELLO, IA REPAIR STATION #K02R959K -	FIRSTANI
DEH BAR	BINNESS IN STREET	NT TAND STREET	rope Oldo
NI 38 OT	WAS DETERMINED	I CERTIFY THAT THIS AIRC INSPECTED IN ACCORDANC INSPECTION AND WAS AIRWORTHY	E WITH ANNUAL TO BE IN
	ME MOLTAVA CLL	TACH HOURS 3932. DATE 4-5-22 WO N	5 14201
* 36 2 Oct	COLAR, MONTICE IN CHAIR STARON AND	MONTICELLO / REGIONAL AIRPOR FAA CERTIFIED REPAI	r MONTICELLO, IA

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		propeller	
	I CER	THY THAT THIS AIRGRAFT/ENGINE HAS BEEN	PROPERTY THAT THE ARGON
	INSPEC	PECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION	INSPECTION AND WAS DEAD
		40148	and the same of th
	DATE_S	Opino	TACH MOURS
	BY	MONTICELLO AVIATION, INC. REGIONAL AIRPORT, MONTICELLO IA	MOUSE MOUSE YE
	FA	CERTIFIED REPAIR STATION #K02R959K	Dazla
		I CERTIFY	THAT THIS AIRCRAFT/ENGINE HAS BEEN
		INSPEC	N ACCORDANCE WITH ANNUAL/16 SECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION
-		TACH HOUR	4098.9
			-24_W.O. NO. 14605
		BY	MONITCELLO AVIATION-INC.
			ONAL AIRPORT, MONTICELLO, IA

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE



